

StressCheck 12.0

StressCheck Toolbar Guide


In this document, a snapshot of each toolbar and its associated icons is provided. For a full description of the StressCheck GUI, refer to [GUI Standards & Layout Overview](#).



Main toolbar



STRESSCHECK




For more details, refer to the [Main Toolbar Overview](#).

Attributes toolbar



STRESSCHECK®




For more details, refer to the [Attributes Toolbar Overview](#).

Display Options toolbar



STRESSCHECK




For more details, refer to the [Display Options Toolbar Overview](#).

Views toolbar



STRESSCHECK®




For more details, refer to the [Views Toolbar Overview](#).

Display Objects toolbar



STRESSCHECK




For more details, refer to the [Display Objects Toolbar Overview](#).

Edit toolbar



STRESSCHECK®



For more details, refer to the [Edit Toolbar Overview](#).